

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

Figure 1




Figure 2




Figure 3





Figure 4




Figure 5




Figure 6




Figure 7






Figure 8

---

1  
Thu Apr 8 21:38:25 2004

2  
Cefepime , ID Code: 4640001

3  
Security code: 8995, Checksum: 6670 vs 6670 OK

4  
Status: EXPIRED

5  
Hours elapsed since LifeTrack start: 52

6  
Hours run before expiration: 11, Average temperature: 29.2 +/- 5.5 C  
Hours run since expiration: 41, Average temperature: 25.2 +/- 0.6 C

7  
Temperature logger (degrees C):  
Logger frequency: 0.5 hours, total logger time: 11.5 hours

8  
Temperatures recorded before expiration:

[- 52.5 hr.]	0,	0,	0,	0,	0,	0,	0,	37,	40,	41,
[- 47.5 hr.]	41,	41,	41,	40,	40,	41,	40,	41,	41,	40,
[- 42.5 hr.]	40,	40,	41,							

9  
Logger expired on Wed Apr 7 04:38:25 2004 (local time), 41 hours ago.

---

Figure 9

